



## GYM DIVIDER CURTAIN WARRANTIES

IPDC975	Key Operated Power Winch	2 year Limited Warranty
IPGTS9	Wireless Controller	1 year Limited Warranty
IPGTS1	Wireless Remote Recvr Drive System	1 year Limited Warranty 5 year Limited Warranty
	Curtain Fabric	1 year Limited Warranty

### WARRANTY INFORMATION

All IPI by Bison products are warranted against manufacturing defects at the time of delivery. In addition, most products are covered by warranty periods stated in the description of the product. Where listed as "limited", warranties cover damage or failure that occurs during the course of "normal or intended use" of the warranted product. Normal or intended use is described as activity that is necessary for the participation in the sport for which the equipment is designed.

IPI by Bison limited warranties do not cover any damage or failure that is the direct or indirect result of any use that is not deemed in the sole discretion of IPI by Bison to be "normal and intended use".

When warranties are stated as "unconditional" or "unconditional replacement", the above stated limitations do not normally apply.

Whether or not stated as such, all IPI by Bison warranties allow IPI by Bison to repair or replace warranted products at IPI by Bison's sole option.

Normal deterioration of products due to weather, wear and tear, or other causes that do not affect functional use are not covered by IPI by Bison warranties, regardless of type of stated warranty.

All warranties are valid only when product is used in the intended application as outlined in IPI by Bison's printed literature, when installed according to IPI by Bison's instructions and when matched with compatible components as described in IPI by Bison's literature.

Due to the abusive nature of pay-to-play facilities, unless specifically agreed to in writing, IPI by Bison products carry no warranty except for obvious manufacturing defects when used in a facility where players pay an individual or group fee to use IPI by Bison equipment.

IPI by Bison will pay ground freight only to repair or replace defective merchandise. Unless otherwise stated, IPI by Bison will not assume any liability for labor costs incurred for removal or replacement of product replaced or repaired under warranty.